

## SHIELD PRODUCTS

### Wet Film Thickness Gage

#### Comb Type

The comb is ruler – shaped gage with two supports at each end of its sides, having tabs of varying lengths.

#### Procedure:

- For measuring, push the comb gauge perpendicularly into the film using the measuring range that corresponds to the expected film thickness.
- Remove the comb gauge from the coating.
- The wet film thickness will fall between the clearance of the shortest tab that is wet and the clearance of the next shortest tab that is dry.

These gauges are inexpensive but very efficient.

You should use the mil gauge whenever possible.

They will save you money and improve quality of your work.

We have these in stock. \$2.50 ea. Include with your order.

Regards,

Bob Diefendorf

Shield Products